Town of Yucca Valley PLANNING COMMISSION STAFF REPORT

To: Honorable Chair and Planning Commissioners

From: Jared Jerome, Associate Planner

Jared Jerome, Associate Planner

Date: March 2, 2022 Meeting Date: March 8, 2022

Subject: Western Joshua Tree (WJT) Permit 030-22, 7516 Barberry Avenue, Yucca

Valley CA. APN: 0587-151-14; Encroach Within Ten (10) Feet of One (1)

Western Joshua Trees.

Recommendation:

That the Planning Commission approve the application for WJT Permit 030-22, encroach within ten (10) feet of one (1) Western Joshua Trees, based upon guidance from the California Department of Fish & Wildlife that sewer project ground disturbing activity may encroach within ten (10) feet of a Western Joshua Tree.

Prior Review

There has been no prior review of this matter.

Executive Summary

Native plant permit applications are acted upon by the Planning Commission for review and action at this time.

Order of Procedure

Request Staff Report
Request Public Comment
Council Discussion/Questions of Staff
Motion/Second
Discussion on Motion
Call the Question

Discussion

Applicant: S.C. Backhoe Services Inc. Address: 7516 Barberry Avenue

APN: 0587-151-14

Zoning: Residential, Single Family (R-S-2)

Parcel Size: 0.89 acres

An application has been filed to encroach within ten (10) feet of one (1) Western Joshua Tree during ground disturbing activity for a sewer line connection. The waste line going into the

residence is within ten (10) feet of two Western Joshua Trees identified as #2 in the attached documentation. Western Joshua Tree #2 is considered a Class 2, which is between 1 and 4 meters in height.

The California Department of Fish & Wildlife has provided guidance to Town staff indicating that sewer connection projects may disturb the ground within ten (10) feet of a Western Joshua Tree if the project proponent has paid the highest applicable mitigation fee as if the tree were to be removed. The project proponent has paid the mitigation fee to remove the tree.

Section 9.56.070 of Ordinance 291 requires photos, descriptions of the trees, and a letter from the applicant's arborist; which are attached to this report.

Alternatives

Staff recommend no alternative actions. The application is consistent with the Town's adopted standards.

Fiscal Impact

Applicant has paid all permit fees and California Fish & Wildlife mitigation fees. Please see attached receipt for more detail.

Attachments:

ORD 291 Joshua Trees WJT 030-22 7516 Barberry Avenue Complete 9.60 Permit Procedures

Attachment: WJT 030-22 7516 Barberry Avenue Complete (4244: Western Joshua Tree (WJT) Permit 030-22, 7516 Barberry Avenue)



Western Joshua Tree Application

_____ Reason for Denial .


Date R	eceived	2/14/22
Case	WIT	030-22
Ву	Ev	m

	_
General Information	
APPLICANT 5.C. BACKLER SELVICES Noc. Phone 160.808-3077	_
Mailing Address 59485 amphouse ST. Email Schotu B70 BMALL. Con	1
City Julian Valley State CA Zip 92284	
PROPERTY OWNER DEALSTRON Phone	
Mailing Address 7516 BURBERRY ADE Email	
City Vuecu Varey State Ost Zip 97284	
Address/Location of Plants 75/6 BALBERRY AVE. VULLA VALLEY CH.	
Desert Native Plant Specialist MARIANA UNBURL	
Project Information	
TYPE OF PLANT # OF PLANTS BEING # OF PLANTS BEING BEING BEING DESTROYED # OF PLANTS BEING TRANSPLANTED BEING TRIMMED # DIAMETER MITIGATION FE REMOVAL	
WESTERN JOSHUA TREE (Yucca brevifolia) WESTERN JOSHUA TREE (Yucca brevifolia) \$500.00 \$525.	00
Reason for removal	
Property owner signature Date //-22:0/	
Staff Use Only Issuance Date: Issued By:	
Approved as shown on plot plan photos Total Fees:	

PLOT PLAN

NAME NEAL	DELALSTRE	Mc	fear marriage		expending a beginning of the Park Service	
PROJECT ADDRESS	-7514	BARBERRY	AJE.		9 .*	6.60
ASSESSOR PARCEL N	10. 050-	7-151 6	9			

IF YOUR LOT IS NOT RECTANGULAR, PLEASE DRAW CORRECT DIMENSIONS AND SHAPE



FRONT PROPERTY LINE STREET



Native Plant Permit Application

Date Received	
Ву	
Case #	

		TO THE RESERVE AS A STATE OF THE RESERVE AS			The second second second		
General Informati	on						
0	A 77 a			71			=
APPLICANT S	=						
Mailing Address	59485	Campo	anula St	Email_SCC	intu8	160am	ailocom
city YUCCO Valley State CA zip 92284							
PROPERTY OWNER	· NEAR	- PEAL	STROW	Phone	ion in the state of		
Mailing Address _	75/6]	Barber	ry Ave.	Email	and the second angle shapes by		
City YUCCO	Valle	1		State			284
Address/Location	of Plants _	1516	Barber	y Ave.	yucca	valk	y CA
Project Information	on	anii in anii anii anii anii anii anii a					
TYPE OF PLANT	# OF PLANTS BEING DESTROYED	# BEING RI	ELOCATED OFF-SITE	# BEING PROTECTED IN PLACE	# BEING TRIMMED	HEIGHT	DIAMETER
MOJAVE YUCCA	1	1		2	1	4	51
JOSHUA TREE				10		151	10
OUR LORDS CANDLE				0		(1)	0
CALIFORNIA JUNIPER				0		A	6
PINON PINE				8		X	0
PARRY'S NOLINA				0		0	
Reason for relocation or removal Property owner signature Date 9.10-21							
Staff Use Only ssuance Date: Issued By:							
approved as shown on plot plan photos Expiration							

Google Maps 7516 Barberry Ave



Map data @2022 , Map data @2022 20 ft

Google Maps 7516 Barberry Ave



Image capture: Mar 2021 © 2

© 2022 Google


ERIC PEALSTROM 15491 PASADENA AVE #51 TUSTIN, CALIFORNIA 92780

C/O SEAN MOLINA MOLINATRACTORSERVICE@GMAIL.COM 760.861.1108

NATIVE PLANT INVENTORY REPORT SITE MAP WITH PHOTOGRAPHIC CENSUS

This report is for a sewer line connection at 7516 Barberry Drive Yucca, Valley CA. A native plant inventory was performed in October 2021 & January 2022 to evaluate the work area (40 ft within estimated work area) for Joshua Trees (*Yucca brevifolia* ssp. *brevifolia*), a candidate species under the California Endangered Species Act (CESA), effective October 9, 2020. There are no *Yucca schidigera* and *Juniperus californicus* affected by this work.

It is recommended to run the necessary trenching (approximately 12" wide and 3' deep) between the Joshua Trees as shown. If the trenching is run between the trees, the resulting potential root disturbance will stay off of the drip line zone of all three trees and thus cause the least amount of stress and instability to all plants.



CONDUCTED BY: MARINNA WAGNER

WE-13354A

ISA CERTIFIED ARBORIST

Ma Mag

PLANT NUMBER: 1


STATUS (TRANSPLANT, DESTROY, PROTECT): PROTECT IN PLACE

CLASS SIZE: C (POLE = 2 meters)

DRIP LINE RADIUS: Approximately 9 ft

DISTANCE FROM WORK: 131 inches or 10.9 ft

RECOMMENDATION: Given plant size, overall age and adjacency to driveway and street, it is best to stay off this tree as much as possible. 131 inches stays off the drip line and should suffice to allow tree to recover.



NATIVE PLANT A	ASSESSMENT FORM			
CLIENT: Sean Molina	DATE: 10/1			
ADDRESS: 7516 Barberry Ave Yucca Valley, CA 92284				
PLANT #: 1	H: 480-550cm (16-18ft) W: 450-550cm (15-18ft)			
CLASS SIZE: C (greater than 4 m) STATUS: PRESERVED				
SITE FACTORS: Residential				
TOPOGRAPHY: Mostly flat	ASPECT: NE			
SOIL CONDITIONS: sandy				
PREVAILING WIND DIRECTION: SW	WIND EXPOSURE: High			
PAST SITE DISTURBANCES: Unknown	1			
HEALTH AND SPECIES PROFILE				
VIGOR (low/normal/high): Normal to low				
FOLIAGE: Short leaves, good color	CHLOROTIC: No			
PESTS: None visible, some woodpecker damage				
ABIOTIC FACTORS: None visible				
# OF LIVE BRANCHES: 50-60 +/- arms; this is a very old	d plant			
LIVING CONDITION 0=dormant, 2=25% alive, 3=50% al				
# OF PUPS OR SAPLINGS generally up to 1 m is a pup; i				
CROWN DENSITY (sparse/normal/dense): Normal	DRIP LINE RADIUS: 270 (9 ft)			
DODDER/MISTLETOE/MOSS/LICHEN: None	John Entermission End (5 tt)			
SPECIES RISK POTENTIAL (branches/trunk/roots): mod	lerate risk for branch failure due to age			
CROWN AND BRANCHES	icrate risk for prantil randre due to age			
# OF DEAD BRANCHES: 6	MAX BRANCH DIAMETER: 45 cm (1.5 ft)			
# OVER-EXTENDED WEAK ATTACHMENTS: None imme				
PREVIOUS BRANCH FAILURES: 1	salute, sat several poteritally weak			
FIRE OR LIGHTNING DAMAGE: None				
MISSING BARK/CAVITY/NEST/CRACKS: None on branch	hes			
FORMS OF DECAY (CONKS/MUSHROOMS/OOZE/GALL				
TRUNK	5). None			
MISSING BARK/CAVITY/NEST/CRACKS: Woodpecker ho	oles			
FORMS OF DECAY (CONKS/MUSHROOMS/OOZE/GALLS				
LEAN: Straight STAKING OR GUYING REC: Not at this time				
FOR DEAD TREES - ESTIMATED TIME SINCE DEATH: NA				
ROOTS				
	ION: Ok move rocks off the base of trunk			
COLLAR BURIED: No ROOT FLARE CONDITION: Ok, move rocks off the base of trunk DEAD/CAVITY/CRACKS: Not visible				
FORMS OF DECAY (CONKS/MUSHROOMS/OOZE/GALLS): None				
	FROM TRUNK: NA			
SOIL WEAKNESS: Not visible	TROW TRONK, NA			
CONSTRUCTION NOTES				
PUP SEPARATATION OR ROOT DIVIDING: Not recomme	ended			
RECOMMENDED BUIDABLE RADIUS: Stay off drip line v				
plant, this is an old plant and is not in the best health a				
roots within the drip line radius, root system has the p				
ESTIMATED TRANSPLANT SURVIVAL RATE: Do not trans				
FREATMENT RECOMMENDATIONS: Do not cut roots la				
GIGNATURE: MARINNA WAGNER	DATE: 10/4/21			
Ma Man	DATE. 10/4/21			
#WE-13354A ISA CERTIFIED ARBORIST & NATIVE PLAN	NT EVDEDT			
HAVE-133344 ISA CENTIFIED ARBORIST & NATIVE PLAN	NI ENTERNI			

PLANT NUMBER: 2

STATUS (TRANSPLANT, DESTROY, PROTECT): PROTECT IN PLACE; TBD


CLASS SIZE: B (POLE = 2 meters)


DRIP LINE RADIUS: The drip line radius of the pup alone is only about 3 ft however, it likely relies on a portion

of th larger root system from the mother plant.

DISTANCE FROM WORK: 91 inches or 7.6 ft

RECOMMENDATION: Given vigor, health of pup, and that the majority of the root system to the south is undisturbed, it can likely survive some root damage and 7.6 ft should suffice. Dead branches on the ground can be removed if desired or they can be left on site, but it is not recommended to dig up the main trunk as that will disturb the live pup. Instead the main trunk could be cut back if desired for aesthetic reasons.





View facing northeast

View facing southwest standing on street

	NATIVE PLANT A	SSESSM	ENT FOR	M
CLIENT: Sean Molina		DATE: 10,	/1	
ADDRESS: 7516 Barberry Ave Yucca Valley, CA 92284		ASSESSOR(S): MW		
PLANT#: 2		H:274 cm		W: 182 cm (6 ft)
CLASS SIZE: B (1-4m)	STATUS: PRESERVED			
SITE FACTORS: Residential				Western Company of the Company of th
TOPOGRAPHY: Mostly flat		ASPECT: N	NE	
SOIL CONDITIONS: sandy		The second second second		
PREVAILING WIND DIRECTION	I: SW	WIND EXP	POSURE: Hi	gh
PAST SITE DISTURBANCES: Un	known	And the Arrest Actions	The state of the s	9
HEALTH AND SPECIES PROFIL	E			
VIGOR (low/normal/high): No	rmal, good			
FOLIAGE: Long leaves, good co			CHLOROT	IC: No
PESTS: None visible				
ABIOTIC FACTORS: Mother pla	ant is dead, unknown cau	ses, looks	like snappe	ed in the wind
# OF LIVE BRANCHES: 5 on pu				
LIVING CONDITION 0=dorman		ive, 4=75%	alive, 5=10	00% alive: 2
# OF PUPS OR SAPLINGS gene				
CROWN DENSITY (sparse/norm			RADIUS: 9	
DODDER/MISTLETOE/MOSS/L				
SPECIES RISK POTENTIAL (bran		currently		
CROWN AND BRANCHES				
OF DEAD BRANCHES: Many	arms dead 8-10 approx.	MAX BRA	NCH DIAME	TER: 76 cm (30 in)
OVER-EXTENDED WEAK ATT				
PREVIOUS BRANCH FAILURES:			likely due t	o weight and wind
FIRE OR LIGHTNING DAMAGE:				
MISSING BARK/CAVITY/NEST/	CRACKS: None			
FORMS OF DECAY (CONKS/MU		i): None		
TRUNK		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		
MISSING BARK/CAVITY/NEST/	CRACKS: None			
FORMS OF DECAY (CONKS/ML		i): None		Charles of the control of the contro
EAN: Slight	STAKING OR GUYING		at this time	9
FOR DEAD TREES - ESTIMATED				
ROOTS				
COLLAR BURIED: No	ROOT FLARE CONDITION	ON: Ok		and places and a second se
DEAD/CAVITY/CRACKS: None				
FORMS OF DECAY (CONKS/MU	JSHROOMS/OOZE/GALLS): None		
PREVIOUSLY CUT/DAMAGED R			NK: NA	
OIL WEAKNESS: Not visible				
CONSTRUCTION NOTES		·		96-11
UP SEPARATATION OR ROOT	DIVIDING: Not recomme	nded		
		- A - A - A - A - A - A - A - A - A - A	orox. 6-8' fr	om center of plant; it is likely
				th is good and thus recovery from
				e potential to be 10-12' wide.
STIMATED TRANSPLANT SUR				- paramata to be to the wine.
REATMENT RECOMMENDATION				eter
IGNATURE: MARINNA WAGNI		oci trian I	DATE: 10/4	
Ma Man	and the second s		JA11. 10/1	T] 60-36
1 000		T EXPERT		

PLANT NUMBER: 3


STATUS (TRANSPLANT, DESTROY, PROTECT): PROTECT IN PLACE

CLASS SIZE: B (POLE = 2 meters)

DRIP LINE RADIUS: 6 ft

DISTANCE FROM WORK:

RECOMMENDATION: Best to leave in place, this is a healthy plant





Red tape to end of pole is 1 meter. This plant is more than 1 meter away from plant #2 and thus considered an individual.

N	ATIVE PLANT ASSI	ESSMENT FORM			
CLIENT: Sean Molina		DATE: 10/1			
ADDRESS: 7516 Barberry Ave Yucca Valley, CA 92284		ASSESSOR(S): MW			
PLANT#: 3		H: 182 cm (6 ft) W: 182 cm (6 ft)			
CLASS SIZE: B (1-4m) STATUS: PRESERVED					
SITE FACTORS: Residential					
TOPOGRAPHY: Mostly flat		ASPECT: NE			
SOIL CONDITIONS: sandy					
PREVAILING WIND DIRECTION:	SW	WIND EXPOSURE: High			
PAST SITE DISTURBANCES: Unk		Trinib Ext Gootte, riigh			
HEALTH AND SPECIES PROFILE		AMBIECH ROBERT AND			
VIGOR (low/normal/high): Nor	mal. good				
FOLIAGE: Long leaves, good co		CHLOROTIC: No			
PESTS: None visible	01	onzonome. No			
ABIOTIC FACTORS: None	THE TAXABLE THE THE WORLDOOM				
# OF LIVE BRANCHES: 5					
	2=25% alive 3=50% al	ive, 4=75% alive, 5=100% alive: 5			
		more than 1 m can be a separate individual: 1			
CROWN DENSITY (sparse/norm		DRIP LINE RADIUS: 91 cm (3 ft)			
DODDER/MISTLETOE/MOSS/LIG		DRIP LINE RADIOS: 91 CIT (5 It)			
SPECIES RISK POTENTIAL (brand		a company the			
CROWN AND BRANCHES	nes/trunk/roots): None	currently			
		IMAN DRANGU DIAMETER, 04 (22 :-)			
OVER EXTENDED WEAK ATTA	CUNATAITC Name -	MAX BRANCH DIAMETER: 81 cm (32 in)			
OVER-EXTENDED WEAK ATTA		ntiy			
PREVIOUS BRANCH FAILURES: I					
FIRE OR LIGHTNING DAMAGE:					
MISSING BARK/CAVITY/NEST/C		· ·			
FORMS OF DECAY (CONKS/MU:	SHROOMS/OOZE/GALLS	S): None			
TRUNK					
MISSING BARK/CAVITY/NEST/C					
FORMS OF DECAY (CONKS/MUS					
	EAN: Slight STAKING OR GUYING REC: None at this time				
OR DEAD TREES - ESTIMATED	TIME SINCE DEATH: NA				
ROOTS					
COLLAR BURIED: No	ROOT FLARE CONDITI	ON: Ok			
DEAD/CAVITY/CRACKS: None					
ORMS OF DECAY (CONKS/MUS		s): None			
PREVIOUSLY CUT/DAMAGED RO	DOTS: NA DISTANCE	FROM TRUNK: NA			
SOIL WEAKNESS: Not visible					
CONSTRUCTION NOTES					
PUP SEPARATATION OR ROOT [
RECOMMENDED BUIDABLE RAD	DIUS: Stay off drip line, I	best to maintain radius of 6-8' from plant,			
oot system has the potential to	be 10-12' wide				
STIMATED TRANSPLANT SURV	VAL BATE: Not necessar	PN			
REATMENT RECOMMENDATION					
GIGNATURE: MARINNA WAGNE	N	DATE: 10/4/21			
HAVE 133EAA ISA CERTIEIED AR	DODICT & MATRIC DI AAS	T EVDERT			
#WE-13354A ISA CERTIFIED AR	BOKIST & NATIVE PLAN	II EXPERI			


PLANT NUMBER: 4

STATUS (TRANSPLANT, DESTROY, PROTECT): PROTECT IN PLACE

CLASS SIZE: B (POLE = 2 meters)
DISTANCE FROM WORK: 10 ft

RECOMMENDATION: Best to leave in place. Tree is healthy and will likely recover some minor root

disturbance. Given the size of the tree transplant is possible, but with the number of pups it will be difficult.



NATIVE	PLANT A	SSESSM	ENT FOR	M
CLIENT: Sean Molina		DATE: 10/1		
ADDRESS: 7516 Barberry Ave Yucca Valley, CA 92284		ASSESSOR		
		H: 340 cm		W: 305 cm (10 ft)
No contract and contract of the	RESERVED I			
SITE FACTORS: Residential				
TOPOGRAPHY: Mostly flat		ASPECT: N	IE	
SOIL CONDITIONS: sandy				
PREVAILING WIND DIRECTION: SW		WIND EXP	OSURE: Hig	rh
PAST SITE DISTURBANCES: Unknown				
HEALTH AND SPECIES PROFILE				
VIGOR (low/normal/high): Normal, great				**************************************
FOLIAGE: Long leaves, good color			CHLOROTI	C: No
PESTS: No visible				
ABIOTIC FACTORS: None visible				
# OF LIVE BRANCHES: 16				account of the second of the s
LIVING CONDITION 0=dormant, 2=25% alive	, 3=50% ali	ve, 4=75%	alive, 5=10	0% alive: 5
# OF PUPS OR SAPLINGS generally up to 1 m				
CROWN DENSITY (sparse/normal/dense): De			RADIUS: 18	
DODDER/MISTLETOE/MOSS/LICHEN: None				
SPECIES RISK POTENTIAL (branches/trunk/ro	oots): None			
CROWN AND BRANCHES				
# OF DEAD BRANCHES: 0	1	MAX BRAN	NCH DIAME	TER: 60 cm (24 in)
# OVER-EXTENDED WEAK ATTACHMENTS: N				
PREVIOUS BRANCH FAILURES: None				1119 (14-14) (14-14) (14-14) (14-14)
FIRE OR LIGHTNING DAMAGE: None				
MISSING BARK/CAVITY/NEST/CRACKS: None	2			
FORMS OF DECAY (CONKS/MUSHROOMS/O): None		
TRUNK		,		
MISSING BARK/CAVITY/NEST/CRACKS: None	2			**************************************
FORMS OF DECAY (CONKS/MUSHROOMS/O): None		
LEAN: Slight south STAKING O	0.00			
FOR DEAD TREES - ESTIMATED TIME SINCE I	THE RESERVE OF THE PARTY OF THE			
ROOTS				
	RE CONDITIO	ON: Ok		STEENING BUILDING STEENINGS STEENINGS
DEAD/CAVITY/CRACKS: None				
FORMS OF DECAY (CONKS/MUSHROOMS/O	OZE/GALLS): None		
	DISTANCE F		NK: NA	
SOIL WEAKNESS: Not apparent				
CONSTRUCTION NOTES				
PUP SEPARATATION OR ROOT DIVIDING: No	t recomme	nded	************	
RECOMMENDED BUIDABLE RADIUS: Stay of			to stay app	rox. 8' away from plant.
Since this plant is in very good health, the ch				
ESTIMATED TRANSPLANT SURVIVAL RATE: T				0 - 10 mg
TREATMENT RECOMMENDATIONS: Do not o				ter
SIGNATURE: MARINNA WAGNER		oc. man 1	DATE: 10/4	
Ma Mora			271121 10/4	,
#WE-13354A ISA CERTIFIED ARBORIST & NA	ATIVE PLAN	TEXPERT		
MANE TOO ALL IN CERTIFIED ARROUNDING IN	TIVE I LAIN	LAILIN		

PLANT NUMBER: 5

STATUS (TRANSPLANT, DESTROY, PROTECT): PROTECT IN PLACE

CLASS SIZE: B (POLE = 2 meters) DISTANCE FROM WORK: 35 ft

RECOMMENDATION: Best to leave in place, this is a healthy plant.




NATIVE PLA	NT ASSESSMENT FORM			
CLIENT: Sean Molina	DATE: 10/1			
ADDRESS: 7516 Barberry Ave Yucca Valley, CA				
PLANT #: 5	H: 180 cm (6 ft) W: 180 cm (6 ft)			
	ERVED IN PLACE			
SITE FACTORS: Residential				
TOPOGRAPHY: Mostly flat	ASPECT: NE			
SOIL CONDITIONS: sandy	7.07.2011112			
PREVAILING WIND DIRECTION: SW	WIND EXPOSURE: High			
PAST SITE DISTURBANCES: Unknown	THE EN COUNTY INDI			
HEALTH AND SPECIES PROFILE				
VIGOR (low/normal/high): Normal				
FOLIAGE: Long leaves, good color	CHLOROTIC: No			
PESTS: None	CHEONOTIC. NO			
ABIOTIC FACTORS: None				
# OF LIVE BRANCHES: 5				
LIVING CONDITION 0=dormant, 2=25% alive, 3=	50% alive 4=75% alive 5=100% alive: 5			
	a pup; more than 1 m can be a separate individual: all pups?			
CROWN DENSITY (sparse/normal/dense): Norm				
DODDER/MISTLETOE/MOSS/LICHEN: None	Idi Dili Elile NADIOS. 32 dili (3 ti)			
SPECIES RISK POTENTIAL (branches/trunk/roots	e): None			
CROWN AND BRANCHES). None			
# OF DEAD BRANCHES: 1	MAX BRANCH DIAMETER: 50 cm (20")			
# OVER-EXTENDED WEAK ATTACHMENTS: None				
PREVIOUS BRANCH FAILURES: None				
FIRE OR LIGHTNING DAMAGE: None				
MISSING BARK/CAVITY/NEST/CRACKS: None				
FORMS OF DECAY (CONKS/MUSHROOMS/OOZI	E/GALLS): None			
TRUNK	-/ GALLS/. Notice			
MISSING BARK/CAVITY/NEST/CRACKS: None				
FORMS OF DECAY (CONKS/MUSHROOMS/OOZI	E/GALLS): None			
	UYING REC: None			
FOR DEAD TREES - ESTIMATED TIME SINCE DEA	Charles of the Contract of the			
ROOTS	TH. NA			
	ONDITION: OK			
DEAD/CAVITY/CRACKS: None	ONDITION. OK			
FORMS OF DECAY (CONKS/MUSHROOMS/OOZE	E/GALLS): None			
	TANCE FROM TRUNK: NA			
SOIL WEAKNESS: Not visible	TANCE FROM TRONK. NA			
CONSTRUCTION NOTES				
PUP SEPARATATION OR ROOT DIVIDING: Not re	commended			
	tree by at least 6-8 ft; work is approximately 40 ft from tree			
ESTIMATED TRANSPLANT SURVIVAL RATE: Tran				
TREATMENT RECOMMENDATIONS: Do not cut r				
SIGNATURE: MARINNA WAGNER	DATE: 10/4/21			
MA MI	DATE: 10/4/21			
#WE-13354A ISA CERTIFIED ARBORIST & NATIV	E DI ANT EYDERT			
WAL-13934W ISW CEVILLED WEDOKIST OF INVITA	L L LANT LAFLAT			

PLANT NUMBER: 6

STATUS (TRANSPLANT, DESTROY, PROTECT): PROTECT IN PLACE

CLASS SIZE: C (POLE = 2 meters)
DISTANCE FROM WORK: 20 ft

RECOMMENDATION: Best to leave in place, this is a healthy plant and is contributing to the seed bank.




NATIVE PLANT A	SSESSMENT FORM			
CLIENT: Sean Molina	DATE: 1/4/22			
ADDRESS: 7516 Barberry Ave Yucca Valley, CA 92284	ASSESSOR(S): MW			
PLANT #: 6	H: 5 m (16 ft) W: 3.2 m (10.5 ft)			
CLASS SIZE: C (4+ m) STATUS: PRESERVED				
SITE FACTORS: Residential				
TOPOGRAPHY: Mostly flat	ASPECT: NE			
SOIL CONDITIONS: Sandy	7/8/12011/12			
PREVAILING WIND DIRECTION: SW	WIND EXPOSURE: High			
PAST SITE DISTURBANCES: Unknown	TVIND EXI GOOKETING!			
HEALTH AND SPECIES PROFILE				
VIGOR (low/normal/high): Normal				
FOLIAGE: Good color, normal	CHLOROTIC: No			
PESTS: None	CHECKOTIC. NO			
ABIOTIC FACTORS: None				
# OF LIVE BRANCHES: 40 +/-				
LIVING CONDITION 0=dormant, 2=25% alive, 3=50% al	live 4=75% alive 5=100% alive: 5			
# OF PUPS OR SAPLINGS generally up to 1 m is a pup;				
CROWN DENSITY (sparse/normal/dense): Normal	DRIP LINE RADIUS: 4.5 m (15 ft)			
DODDER/MISTLETOE/MOSS/LICHEN: None	DRIF LINE NADIOS. 4.5 III (15 IL)			
SPECIES RISK POTENTIAL (branches/trunk/roots): None				
CROWN AND BRANCHES				
	IMAY BRANCH DIAMETER: 60 cm (1.0 ft)			
# OF DEAD BRANCHES: 3 MAX BRANCH DIAMETER: 60 cm (1.9 ft)				
# OVER-EXTENDED WEAK ATTACHMENTS: None PREVIOUS BRANCH FAILURES: None				
FIRE OR LIGHTNING DAMAGE: None				
MISSING BARK/CAVITY/NEST/CRACKS: None				
FORMS OF DECAY (CONKS/MUSHROOMS/OOZE/GALL:	C). None			
TRUNK	s). Notie			
ALCOHOLOGY TO THE PROPERTY OF				
MISSING BARK/CAVITY/NEST/CRACKS: None	C). No. 10			
FORMS OF DECAY (CONKS/MUSHROOMS/OOZE/GALL				
LEAN: South STAKING OR GUYING				
FOR DEAD TREES - ESTIMATED TIME SINCE DEATH: NA				
ROOTS	ou or i i i i i			
	ON: OK, some site erosion around the base			
DEAD/CAVITY/CRACKS: None	2) Al			
FORMS OF DECAY (CONKS/MUSHROOMS/OOZE/GALLS				
	FROM TRUNK: NA			
SOIL WEAKNESS: Not visible				
CONSTRUCTION NOTES				
PUP SEPARATATION OR ROOT DIVIDING: Not recomme				
	at least 15 ft especially to the south where wide roots are			
ESTIMATED TRANSPLANT SURVIVAL RATE: Transplant i				
TREATMENT RECOMMENDATIONS: Do not cut roots la				
SIGNATURE: MARINNA WAGNER	DATE: 1/4/22			
Ma May				
#WVE-13354A ISA CERTIFIED ARBORIST & NATIVE PLANT EXPERT				

PLANT NUMBER: 7

STATUS (TRANSPLANT, DESTROY, PROTECT): PROTECT IN PLACE

CLASS SIZE: B (POLE = 2 meters)
DISTANCE FROM WORK: 25 ft

RECOMMENDATION: Best to leave in place, this is a healthy plant and is contributing to the seed bank.



NATIVE PLANT	ASSESSMENT FORM				
CLIENT: Sean Molina	DATE: 1/4/22				
ADDRESS: 7516 Barberry Ave Yucca Valley, CA 92284					
PLANT #: 7	H: 2.4 m (7.8 ft) W: 2.4 m (7.8 ft)				
CLASS SIZE: B (1-4 m) STATUS: PRESERVED					
SITE FACTORS: Residential					
TOPOGRAPHY: Mostly flat	ASPECT: NE				
SOIL CONDITIONS: Sandy					
PREVAILING WIND DIRECTION: SW WIND EXPOSURE: High					
PAST SITE DISTURBANCES: Unknown	11				
HEALTH AND SPECIES PROFILE					
VIGOR (low/normal/high): Normal	THE RESIDENCE OF THE PROPERTY				
FOLIAGE: Good color, very long leaves	CHLOROTIC: No				
PESTS: None					
ABIOTIC FACTORS: None					
# OF LIVE BRANCHES: 11					
LIVING CONDITION 0=dormant, 2=25% alive, 3=50% a	alive, 4=75% alive, 5=100% alive: 5				
# OF PUPS OR SAPLINGS generally up to 1 m is a pup;					
CROWN DENSITY (sparse/normal/dense): Normal	DRIP LINE RADIUS: 1.8 m (6 ft)				
DODDER/MISTLETOE/MOSS/LICHEN: None	the state of the s				
SPECIES RISK POTENTIAL (branches/trunk/roots): Nor	ne				
CROWN AND BRANCHES					
# OF DEAD BRANCHES: 1	MAX BRANCH DIAMETER: 80 cm (2.6 ft)				
# OVER-EXTENDED WEAK ATTACHMENTS: None					
PREVIOUS BRANCH FAILURES: None					
FIRE OR LIGHTNING DAMAGE: None					
MISSING BARK/CAVITY/NEST/CRACKS: None					
FORMS OF DECAY (CONKS/MUSHROOMS/OOZE/GAL	LS): None				
TRUNK					
MISSING BARK/CAVITY/NEST/CRACKS: None					
FORMS OF DECAY (CONKS/MUSHROOMS/OOZE/GAL	LS): None				
LEAN: South STAKING OR GUYING REC: None					
FOR DEAD TREES - ESTIMATED TIME SINCE DEATH: NA					
ROOTS					
COLLAR BURIED: No ROOT FLARE CONDIT	TION: OK				
DEAD/CAVITY/CRACKS: None					
FORMS OF DECAY (CONKS/MUSHROOMS/OOZE/GALI	LS): None				
PREVIOUSLY CUT/DAMAGED ROOTS: NA DISTANCE FROM TRUNK: NA					
SOIL WEAKNESS: Not visible					
CONSTRUCTION NOTES					
PUP SEPARATATION OR ROOT DIVIDING: Not recomm	nended				
RECOMMENDED BUIDABLE RADIUS: Stay off of tree b					
ESTIMATED TRANSPLANT SURVIVAL RATE: Transplant					
TREATMENT RECOMMENDATIONS: Do not cut roots I	arger than 1.5 inches diameter				
SIGNATURE: MARINNA WAGNER	DATE: 1/4/22				
Ma Mag					
#XVE-13354A ISA CERTIFIED ARBORIST & NATIVE PLANT EXPERT					



Town of Yucca Valley Community Development/Public Works Depts 58928 Business Center Dr Yucca Valley CA 92284 Receipt # 29946

Date 2/16/2022

Rcvd By Wendy Ortiz


Received From SC Backhoe Services Inc 59485 Campanula St Yucca Valley, CA 92284

(760) 808-3077

Customer Number	Name	Payment Type	Check/Auth #	Amount Received
10105	SC Backhoe Services Inc	Check	#1418	1,025.00

Description: NPP App & WJT 030-22 MItigation


WJT Take Permit Fees 500.00 Wildlife Mitigation State Pass Thru Fees 525.00



THIS MAP IS FOR THE PURPOSE OF AD VALOREM TAXATION ONLY, Ptn. Yucca Corral Ranchos, Tract No. 3967 M.B. 54/30-32 Town of Yucca Valley 05 Tax Rate Area 23000

0587 - 1 J





Ptn. N.W.1/4, Sec. 1 T.1S., R.5E. Assessor's Map Book 0587 Page 15 San Bernardino County REVISED 09/20/17 KC Packet Pg. 34

February 2005