



LEGEND

- TOP OF BANK
- - - NATURAL GROUND
- PROPOSED INVERT
- ▲ BOTTOM CONTROL
- ▲ CULVERT
- FACILITY NUMBER
- REGIONAL FACILITY
- SECONDARY FACILITY
- LOCAL FACILITY
- SBC SOFT-BOTTOM CHANNEL
- RLC ROCK-LINED CHANNEL
- CLC CONCRETE-LINED CHANNEL
- MFP MANAGED FLOODPLAIN
- RCP REINFORCED CONCRETE PIPE
- RRSS ROCK-RETTED SIDE SLOPES

SAN BERNARDINO COUNTY
 FLOOD CONTROL DISTRICT
 YUCCA VALLEY MASTER PLAN OF DRAINAGE
CHIPMUNK WASH (V01-01)
HILLCREST WASH (V01-03)
 STA. 0+00 TO STA. 37+83
 STA. 0+00 TO STA. 41+25

SCALE
 H: 1"=1000'
 V: 1"=40'

John M. Tettemer
 JOHN M. TETTEMER & ASSOCIATES, LTD.
 ENGINEERING MANAGEMENT PLANNING
 3151 Arroyo Avenue, Suite 0-1 Costa Mesa, California 92626

DATE
 SEPT 1998
 FIGURE
 35