


**LEGEND**

- TOP OF BANK
- - - NATURAL GROUND
- PROPOSED INVERT
- ▲ BOTTOM CONTROL
- ▲ CULVERT
- (Y01) FACILITY NUMBER
- REGIONAL FACILITY
- SECONDARY FACILITY
- LOCAL FACILITY
- SBC SOFT-BOTTOM CHANNEL
- RLC ROCK-LINED CHANNEL
- CLC CONCRETE-LINED CHANNEL
- STF STREET FLOW
- MFP MANAGED FLOODPLAIN
- RRSS ROCK-RETTED SIDE SLOPES

**SCALE**

H: 1"=1000'  
V: 1"=40'

**SAN BERNARDINO COUNTY**  
**FLOOD CONTROL DISTRICT**  
**YUCCA VALLEY MASTER PLAN OF DRAINAGE**  
**BUENA VISTA WASH**  
**(Y05 & Y05-01)**  
**SAGE CHANNEL (Y06)**  
 STA. 0+00 TO STA. 51+61  
 STA. 0+00 TO STA. 17+25



JOHN M. TETTENER & ASSOCIATES, LTD.  
ENGINEERING MANAGEMENT PLANNING  
3151 Hurway Avenue, Suite 0-1 Costa Mesa, California 92626

DATE  
**SEPT 1998**

FIGURE  
**19**