

LEGEND

- TOP OF BANK
- - - NATURAL GROUND
- - - PROPOSED INVERT
- ▲ BOTTOM CONTROL
- ▲ CULVERT
- (V01) FACILITY NUMBER
- ▬ REGIONAL FACILITY
- ▬ SECONDARY FACILITY
- ▬ LOCAL FACILITY
- SBC SOFT-BOTTOM CHANNEL
- RLC ROCK-LINED CHANNEL
- CLC CONCRETE-LINED CHANNEL
- MFP MANAGED FLOODPLAIN
- RCP REINFORCED CONCRETE PIPE
- RRSS ROCK-RETTED SIDE SLOPES


SAN BERNARDINO COUNTY
 FLOOD CONTROL DISTRICT
 YUCCA VALLEY MASTER PLAN OF DRAINAGE

SIERRA VISTA WASH
(V01 & V01-02)

STA. 110+00 TO STA. 177+07

SCALE

H: 1"=1000'
 V: 1"=40'


John H. Tettemer
 JOHN H. TETTEMER & ASSOCIATES, LTD.
 ENGINEERING MANAGEMENT PLANNING
 3151 Arway Avenue, Suite D-1, Costa Mesa, California 92626

DATE
 SEPT 1998
 FIGURE
 34