



LEGEND

- TOP OF BANK
- NATURAL GROUND
- PROPOSED INVERT
- ▲ BOTTOM CONTROL
- ▲ CULVERT
- Y01 FACILITY NUMBER
- REGIONAL FACILITY
- SECONDARY FACILITY
- LOCAL FACILITY
- SBC SOFT-BOTTOM CHANNEL
- RLC ROCK-LINED CHANNEL
- STF STREET FLOW
- MFP MANAGED FLOODPLAIN
- RCP REINFORCED CONCRETE PIPE
- RRSS ROCK-RETTED SIDE SLOPES

SAN BERNARDINO COUNTY
FLOOD CONTROL DISTRICT
YUCCA VALLEY MASTER PLAN OF DRAINAGE

**HANFORD AVENUE DRAIN
(Y01-01)**

STA. 0+00 TO STA. 29+55

DATE
SEPT 1998

FIGURE
26

John H. Tettemer
John H. Tettemer & Associates, Ltd.
ENGINEERING MANAGEMENT PLANNING
3151 Airway Avenue, Suite Q-1, Costa Mesa, California 92626