



- LEGEND**
- TOP OF BANK
  - - - NATURAL GROUND
  - PROPOSED INVERT
  - ▲ BOTTOM CONTROL
  - ▲ CULVERT
  - (Y01) FACILITY NUMBER
  - REGIONAL FACILITY
  - SECONDARY FACILITY
  - LOCAL FACILITY
  - SBC SOFT-BOTTOM CHANNEL
  - RLC ROCK-LINED CHANNEL
  - CLC CONCRETE-LINED CHANNEL
  - STF STREET FLOW
  - MFP MANAGED FLOODPLAIN
  - RRSS ROCK-RETTED SIDE SLOPES

**SCALE**  
 H: 1"=1000'  
 V: 1"=40'

SAN BERNARDINO COUNTY  
 FLOOD CONTROL DISTRICT  
 YUCCA VALLEY MASTER PLAN OF DRAINAGE

**WARREN VISTA DRAIN  
 (Y02-01)**

STA. 0+00 TO STA. 50+10

DATE  
 SEPT 1998

FIGURE  
 22

*John M. Tetterer*  
 JOHN M. TETTERER & ASSOCIATES, LTD.  
 ENGINEERING MANAGEMENT PLANNING  
 3151 Arroyo Avenue, Suite Q-1 Costa Mesa, California 92626