



LEGEND

- TOP OF BANK
- - - NATURAL GROUND
- PROPOSED INVERT
- ▲ STABILIZER STRUCTURE
- CULVERT
- ⊙ FACILITY NUMBER
- ▬ REGIONAL FACILITY
- ▬ SECONDARY FACILITY
- ▬ LOCAL FACILITY
- SBC SOFT-BOTTOM CHANNEL
- RLC ROCK-LINED CHANNEL
- CLC CONCRETE-LINED CHANNEL
- RCB REINFORCED CONCRETE BOX
- MFP MANAGED FLOODPLAIN
- RRSS ROCK-RETTED SIDE SLOPES

SCALE

H: 1"=1000'
 V: 1"=40'

SAN BERNARDINO COUNTY
 FLOOD CONTROL DISTRICT

YUCCA VALLEY MASTER PLAN OF DRAINAGE

EAST BURNT MTN. WASH (Y03)
EAST BURNT MTN. WASH TRIBUTARY (Y03-01)

STA. 0+00 TO STA. 48+60
 STA. 0+00 TO STA. 53+82

DATE
 SEPT 1998

FIGURE
 23

John M. Tetterer
 JOHN M. TETTERER & ASSOCIATES, LTD.
 ENGINEERING MANAGEMENT PLANNING
 3151 Arroyo Avenue, Suite 0-1 Costa Mesa, California 92626