

SITE PLAN NOTES

1. AVERAGE LOT SLOPE IS LESS THAN 5 %
2. A SOIL REPORT WILL NOT BE REQUIRED IF THE ADDITIONS PATIOS AND ACCESSORY BUILDINGS IF THE APPLICANT SIGNS THE CITY STAMPS ON THE PLANS AGREEING TO SECURE A SOIL REPORT IF THE INSPECTOR DETECTS PROBLEMS.
3. PRIOR TO FINAL INSPECTION, THE LICENSED CONTRACTOR, ARCHITECT OR ENGINEER IN RESPONSIBLE CHARGE OF THE OVERALL CONSTRUCTION MUST PROVIDE TO THE BUILDING DEPARTMENT OFFICIAL WRITTEN VERIFICATION THAT ALL APPLICABLE PROVIDED FROM THE GREEN BUILDINGS STANDARDS CODE HAVE BEEN IMPLEMENTED AS PART OF THE CONSTRUCTION CGC 102.3
4. COMPLIANCE WITH THE DOCUMENTATION REQUIREMENTS OF THE 2016 ENERGY EFFICIENCY STANDARDS IS NECESSARY FOR THIS PROJECT. REGISTERED, SIGNED AND DATED COPIES OF THE APPROPRIATE CF1R, CF2R AND CF3R FORMS SHALL BE MADE AVAILABLE AT NECESSARY INTERVALS FOR BUILDING INSPECTOR REVIEW. FINAL COMPLETED FORMS WILL BE AVAILABLE FOR THE BUILDING OWNER.

7344 WAMEGO TR
YUCCA VALLEY

ADDRESS:

PROFESSIONAL SEAL:



REVISIONS DATE

PROJECT NUMBER CLIENT NAME

DRAWN BY CHECKED BY

SCALE DRAWING NUMBER

1" = 100'

DRAWING TITLE:

PHOTOMETRIC PLAN

